
HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS



MERCER COUNTY BRIDGE No. 2631 Spanning Pine Run at Cribbs Road Mercer Vicinity Mercer County Pennsylvania HAER No. PA-225

March and April, 1993

Photographer: Joel S. Dzodin		
DA 225 1	CENIED AT CETTING OF MEDGED COTINITY DDI	

CHORDS. FACING NORTHEAST.

PA-225-1	GENERAL SETTING OF MERCER COUNTY BRIDGE NO. 2631. FACING NORTH.
PA-225-2	VIEW OF NORTHERN BRIDGE APPROACH ALONG CRIBBS ROAD. FACING SOUTH.
PA-225-3	VIEW OF THE SOUTHERN BRIDGE APPROACH ALONG CRIBBS ROAD. FACING NORTH.
PA-225-4	VIEW OF THE EASTERN BRIDGE ELEVATION FROM PINE RUN. FACING WEST.
PA-225-5	VIEW OF THE WESTERN BRIDGE ELEVATION FROM PINE RUN. FACING EAST.
PA-225-6	VIEW ACROSS TRAFFIC LEVEL. FACING NORTH.
PA-225-7	VIEW OF NORTHERN STONE ABUTMENT, SHOWING UNDERSIDE OF BRIDGE DECK, FLOOR BEAMS, STRINGERS, AND BOTTOM LATERAL BRACING. FACING SOUTH.
PA-225-8	VIEW OF SOUTHERN STONE ABUTMENT, SHOWING UNDERSIDE OF BRIDGE DECK, LOWER CHORDS, FLOOR BEAMS, STRINGERS, AND BOTTOM LATERAL BRACING. FACING WEST.
PA-225-9	DETAIL VIEW OF EASTERN ELEVATION, SHOWING UPPER AND LOWER CHORDS, DECK, DIAGONAL TORSION RODS, AND WRAP-AROUND VERTICAL RODS CONNECTED TO FLOOR BEAMS. FACING WEST.
PA-225-10	DETAIL VIEW OF WESTERN UPPER CHORD, SHOWING WRAP-AROUND VERTICAL AND DIAGONAL TORSION BARS. FACING NORTH.
PA-225-11	DETAIL VIEW OF LOWER CHORD AND CONNECTIONS OF VERTICAL AND DIAGONAL BARS TO FLOOR BEAM ON WESTERN ELEVATION. FACING EAST.
PA-225-12	DETAIL VIEW OF NORTHWEST FOUNDATION, SHOWING BRIDGE BEARING SEAT AND THREADED U-BOLT CONNECTION OF UPPER AND LOWER BRIDGE